

15A NCAC 02D .0306 EMISSION REDUCTION PLAN: WARNING LEVEL

(a) General

- (1) There shall be no open burning by any person of trade waste, refuse, vegetation, or debris in any form.
- (2) The use of incinerators for the disposal of solid waste or liquid waste shall be prohibited.
- (3) Persons operating fuel burning equipment which requires boiler lancing or soot blowing shall perform such operations only between 12-noon and 4:00 p.m.
- (4) Persons operating motor vehicles should minimize their use through car pools and increased use of public transportation.

(b) Source Curtailment. Any person responsible for the operation of a source of air pollution shall take all required control actions for the warning level that are listed below:

- (1) Operators of coal or oil fired electric power generating facilities shall:
 - (A) use fuels having the lowest ash and sulfur content,
 - (B) perform boiler lancing and soot blowing between 12-noon to 4:00 p.m., and
 - (C) divert electric power generating to facilities outside of warning area;
- (2) Operators of coal or oil fired process steam generating facilities shall:
 - (A) use fuels having the lowest ash and sulfur content,
 - (B) perform boiler lancing and soot blowing between 12-noon to 4:00 p.m.,
 - (C) reduce steam load demands consistent with continuing plant operations, and
 - (D) prepare to use the plan of action to be taken if an emergency develops;
- (3) Operators of manufacturing industries of the following classifications: primary metal industries; petroleum refining and related industries; chemical and allied products industries; paper and allied products industries; glass, clay and concrete products industries shall:
 - (A) reduce air pollutants from manufacturing operations by, if necessary, assuming reasonable economic hardship by postponing production and related operations;
 - (B) defer trade waste disposal operations which emit particles, gases, vapors, or malodorous substances;
 - (C) reduce heat load demands for processing consistent with continuing plant operations; and
 - (D) perform boiler lancing or soot blowing between 12-noon to 4:00 p.m.;
- (4) Municipal and commercial refuse disposal operations shall stop incinerating waste;
- (5) Other persons requested by the Commission to prepare a preplanned abatement plan shall take all required control actions for the warning level contained in their plan.

*History Note: Authority G.S. 143-215.3(a)(1); 143-215.3(a)(12);
Eff. February 1, 1976;
Amended Eff. July 1, 1984; December 1, 1976.*